

## Repair kit for basin/urinal cartridge

Ref. 753005

For TEMPOSTOP basin/urinal



### DESCRIPTION

Repair kit for basin/urinal cartridge - [Ref. 753005](#)

Repair kit for TEMPOSTOP basin/urinal cartridge.  
Time flow ~7 seconds.  
Until 2022.

### ADVANTAGES



Easy to maintain

### TECHNICAL CHARACTERISTICS

Repair kit for basin/urinal cartridge - [Ref. 753005](#)

Technology

Time flow

---

